

Lead-Based Paint Inspection Report



| Location of Inspection/ Building Owner: | 523 Route 20 New Lebanon, New York |
|--|--|
| Performed for: | Town of New Lebanon 14755 Route 22, PO Box 328 New Lebanon New York 12125 |
| Results of Inspection: | Lead-based paint was found in the following locations: Exterior orange walls |
| Alpine Project #: Date of Testing: Report Date: Report Expiration Date: | 24-30525-A October 4, 2024 October 15, 2024 October 4, 2025 |
| Inspected By: | Alpine Environmental Services, Inc. 438 New Karner Road Albany, New York 12205 (518) 250-4047 |
| Inspector: | Paul Van Zandt USEPA Certified Risk Assessor NY-R-1262-2 |
| Instrument: Data Interpretation: Source: Sourced On: | Niton XLp 301A USEPA PCS Cadmium 109, 40mCi 11/05/20 |

Description:

The Town of New Lebanon hired Alpine Environmental Services to perform a lead-based paint inspection using X-ray florescence (XRF) of 523 Route 20, New Lebanon, New York. A risk assessment differs from a lead-based paint inspection in that only lead hazards are identified in the risk assessment as opposed to all painted surfaces being tested for a lead inspection.

The building was a single-story, metal structure. There was no basement. The building was formerly used as a fire department. The rooms consisted of former truck bays, meeting room, bathrooms, kitchen social hall and a free store. Windows were factory finished metal. Interior walls were drywall, metal or wood paneling. Floors were concrete throughout. Most interior paint was intact at the time of inspection. The exterior was painted metal.

Conclusion:

The Occupational Safety and Health Administration (OSHA) considers any amount of lead in paint to be a potential hazard. The U.S. Housing and Urban Development (HUD) Guidelines for the Evaluation and Control of Lead-Based Paint in Housing (2012 Revision) define lead-based paint as having a lead content of 1.0mg/cm² as measured by XRF. Alpine Environmental Services, Inc. has concluded through XRF analysis that lead at or above 1.0mg/cm² was not found in the locations tested. However, <u>a detectable amount of lead was found in the orange paint on the exterior of the building</u>.

Recommendations:

If any of the orange paint is disturbed, all applicable OSHA regulations should be followed. If LBP is to remain, it shall be kept in an intact state. If the building will be used as a child occupied facility, all U.S. Housing and Urban Development (HUD) Guidelines for the Evaluation and Control of Lead-Based Paint in Housing (2012 Revision) should be followed.

If Alpine Environmental Services, Inc. can be of further assistance, please contact our office at (518) 250-4047ext. 314.

Sincerely, ALPINE ENVIRONMENTAL SERVICES, INC.

PIVEZ 16

Paul Van Zandt USEPA Certified Lead Risk Assessor

Enclosures: Floor Plans, XRF Data Sheet, EPA Company Certification, EPA Personal Certification

Client: Town of New Lebanon

Prepared by: Alpine Environmental Services, Inc.

| No | Time | FI | Room Rm# | ŧ 9 | d Component | Feature | Condit | Substr | Results | PbC | PbC Error | PbL | PbL Error | PbK | PbK Error | Units | Dpth | Dur |
|----|----------------|----|---------------|-----|-------------|-----------|---------|---------|----------|-------|--------------|-------|--------------|-------|--------------|--------------------|------|------|
| 1 | 10/4/2024 8:57 | | Shutter Calib | rat | 2 | | | | | 1.68 | 0 | 0.24 | 0 | 0 | 0 | cps | | 234 |
| 2 | 10/4/2024 8:58 | | Calibrate | | | | Intact | Metal | Negative | 0.9 | 0.1 | 0.9 | 0.1 | < LOD | 1.2 | mg/cm ² | 1.03 | 3.66 |
| 3 | 10/4/2024 9:00 | | Calibrate | | | | Intact | Metal | Null | 1 | 0.1 | 1 | 0.1 | < LOD | 0.7 | mg/cm ² | 2.67 | 10.4 |
| 4 | 10/4/2024 9:00 | 1 | Meeting Rm | | A Wall | | Intact | Drywall | Negative | < LOD | 0.03 | < LOD | 0.03 | < LOD | 2.25 | mg/cm ² | 1 | 1.36 |
| 5 | 10/4/2024 9:01 | 1 | Meeting Rm | | A Door | Jamb | Intact | Wood | Negative | < LOD | 0.03 | < LOD | 0.03 | < LOD | 2.14 | mg/cm ² | 1 | 1.22 |
| 6 | 10/4/2024 9:01 | 1 | Meeting Rm | | B Door | | Intact | Metal | Negative | < LOD | 0.03 | < LOD | 0.03 | < LOD | 3.36 | mg/cm ² | 1.75 | 1.22 |
| 7 | 10/4/2024 9:02 | 1 | Truck Bay | | Floor | | Cracked | Concr | Negative | < LOD | 0.06 | < LOD | 0.06 | < LOD | 2.75 | mg/cm ² | 2.46 | 2.58 |
| 8 | 10/4/2024 9:03 | 1 | Truck Bay | | D Wall | | Intact | Drywall | Negative | < LOD | 0.03 | < LOD | 0.03 | < LOD | 2.14 | mg/cm ² | 1 | 1.43 |
| 9 | 10/4/2024 9:03 | 1 | Truck Bay | | D Door | to Blr Rm | Intact | Metal | Negative | < LOD | 0.03 | < LOD | 0.03 | < LOD | 2.86 | mg/cm ² | 1 | 1.36 |
| 10 | 10/4/2024 9:04 | 1 | Truck Bay | | A Column | | Intact | Metal | Negative | < LOD | 0.04 | < LOD | 0.04 | < LOD | 3.2 | mg/cm ² | 1.65 | 1.43 |
| 11 | 10/4/2024 9:04 | 1 | Truck Bay | | B Door | Jamb | Intact | Metal | Negative | < LOD | 0.03 | < LOD | 0.03 | < LOD | 3.61 | mg/cm ² | 1 | 1.28 |
| 12 | 10/4/2024 9:05 | 1 | Truck Bay | | B Wall | | Intact | Metal | Negative | < LOD | 0.08 | < LOD | 0.08 | < LOD | 3.01 | mg/cm ² | 1.88 | 1.22 |
| 13 | 10/4/2024 9:05 | 1 | Truck Bay | | B Column | | Intact | Metal | Negative | < LOD | 0.03 | < LOD | 0.03 | < LOD | 4.16 | mg/cm ² | 1 | 1.15 |
| 14 | 10/4/2024 9:06 | 1 | Social Hall | | B Radiator | | Intact | Metal | Negative | < LOD | 0.04 | < LOD | 0.04 | < LOD | 3.28 | mg/cm ² | 2.02 | 1.07 |
| 15 | 10/4/2024 9:07 | 1 | Kitchen Hall | | C Wall | | Intact | Drywall | Negative | < LOD | 0.03 | < LOD | 0.03 | < LOD | 2.55 | mg/cm ² | 1 | 1.36 |
| 16 | 10/4/2024 9:07 | 1 | Kitchen Hall | | C Door | Jamb | Intact | Metal | Negative | < LOD | 0.03 | < LOD | 0.03 | < LOD | 3.39 | mg/cm ² | 1 | 1.22 |
| 17 | 10/4/2024 9:08 | 1 | Kitchen | | C Wall | | Intact | Drywall | Negative | < LOD | 0.03 | < LOD | 0.03 | < LOD | 2.62 | mg/cm ² | 1 | 1.64 |
| 18 | 10/4/2024 9:08 | 1 | Free Store | | A Door | | Intact | Metal | Negative | < LOD | 0.03 | < LOD | 0.03 | < LOD | 3.63 | mg/cm ² | 1 | 1.14 |
| 19 | 10/4/2024 9:08 | 1 | Free Store | | A Door | Jamb | Intact | Metal | Negative | < LOD | 0.04 | < LOD | 0.04 | < LOD | 3.91 | mg/cm ² | 1 | 1.07 |
| 20 | 10/4/2024 9:09 | 1 | Free Store | | C Door | | Intact | Metal | Negative | < LOD | 0.03 | < LOD | 0.03 | < LOD | 3.57 | mg/cm ² | 1 | 1.15 |
| 21 | 10/4/2024 9:10 | 1 | Free Store | | C Wall | | Intact | Metal | Negative | < LOD | 0.05 | < LOD | 0.05 | < LOD | 2.71 | mg/cm ² | 1 | 1.08 |
| 22 | 10/4/2024 9:11 | 1 | Bath 2 | 1 | Wall | | Intact | Drywall | Negative | < LOD | 0.03 | < LOD | 0.03 | < LOD | 2.66 | mg/cm ² | 1 | 1.43 |
| 23 | 10/4/2024 9:11 | 1 | Bath 2 | 2 | Wall | | Intact | Drywall | Negative | < LOD | 0.03 | < LOD | 0.03 | < LOD | 2.27 | mg/cm ² | 1 | 1.43 |
| 24 | 10/4/2024 9:12 | 1 | Bath 3 | 3 | Wall | | Intact | Drywall | Negative | < LOD | 0.03 | < LOD | 0.03 | < LOD | 2.44 | mg/cm ² | 1 | 1.36 |
| 25 | 10/4/2024 9:13 | 1 | Exterior | | A Wall | | Peeling | Stucco | Negative | < LOD | 0.03 | < LOD | 0.03 | < LOD | 2.48 | mg/cm ² | 1 | 1.22 |
| 26 | 10/4/2024 9:14 | 1 | Exterior | | A Wall | | Intact | Metal | Negative | < LOD | 0.04 | < LOD | 0.04 | < LOD | 3.12 | mg/cm ² | 1 | 1.15 |
| 27 | 10/4/2024 9:14 | 1 | Exterior | | A Door | Jamb | Peeling | Wood | Negative | < LOD | 0.03 | < LOD | 0.03 | < LOD | 2.26 | mg/cm ² | 1 | 1.15 |
| 28 | 10/4/2024 9:16 | 1 | Exterior | | B Wall | Orange | Intact | Metal | Negative | 0.6 | 0.2 | 0.6 | 0.2 | < LOD | 3 | mg/cm ² | 1.48 | 1.3 |

| Clien Prep | t: Town of New L ared by: Alpine E | eb nvi | anon ronmenta | al Servi | ces | , Inc. | | 5 New Le | 23 Route ebanon, N | 20 ew York | | | | | | | Proje | ct# 24- | 30525-A |
|---------------|---------------------------------------|-----------|------------------|----------|-----|-----------|---------|-------------|-----------------------|---------------|-------|--------------|-------|--------------|-------|--------------|--------------------|---------|---------|
| No | Time | FI | Room | Rm# | Sd | Component | Feature | Condit | Substr | Results | PbC | PbC Error | PbL | PbL Error | PbK | PbK Error | Units | Dpth | Dur |
| 29 | 10/4/2024 9:17 | 1 | Exterior | | В | Door | | Intact | Metal | Negative | < LOD | 0.03 | < LOD | 0.03 | < LOD | 3.44 | mg/cm ² | 1 | 1.15 |
| 30 | 10/4/2024 9:20 | 1 | Exterior | | D | Door | Jamb | Peeling | Metal | Negative | < LOD | 0.03 | < LOD | 0.03 | < LOD | 3.98 | mg/cm ² | 1 | 1.23 |

0.9

1

0.1

1

| 31 | 10/4/2024 9:21 | Calibrate | Intact | Metal | Negative |
|----|----------------|-----------|--------|-------|----------|
| 32 | 10/4/2024 9:22 | Calibrate | Intact | Metal | Null |

0.1 0.9 0.1 < LOD 1.1 mg/cm^2 1.08 4.44

0.1 < LOD 0.93 mg/cm² 2.64 6.45



United States Environmental Protection Agency

This is to certify that

Paul Van Zandt



has fulfilled the requirements of the Toxic Substances Control Act (TSCA) Section 402, and has received certification to conduct lead-based paint activities pursuant to 40 CFR Part 745.226 as:

Risk Assessor

n of: In the

All EPA Administered Lead-based Paint Activities Program States, Tribes and Territories

This certification is valid from the date of issuance and expires March 07, 2025

Ben Ponetta

Ben Conetta, Chief Chemicals and Multimedia Programs Branch

LBP-R-1262-2

Certification #

February 28, 2022

Issued On



United States Environmental Protection Agency

This is to certify that

Alpine Environmental Services, Inc.

has fulfilled the requirements of the Toxic Substances Control Act (TSCA) Section 402, and has received certification to conduct lead-based paint activities pursuant to 40 CFR Part 745.226

In the Jurisdiction of:

All EPA Administered Lead-based Paint Activities Program States, Tribes and Territories

This certification is valid from the date of issuance and expires February 21, 2025

LBP-113-2

Certification #

January 21, 2022

Issued On



M.J. la Pro

Michelle Price, Chief Lead, Heavy Metals, and Inorganics Branch